



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name			Sycamore			System ID Number:		IL0370550		Current Inventory Date:		4/1/2025			
*Please enter totals in the empty box next to each category	Total Service lines:		7553	Total Lead:	5	Total Non-Lead:	7548	Total Galvanized Requiring replacement:		0	Total Unknown:	0	Website link to Material Inventory:		https://cityofsycamore.com/194/Water-Division	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Copper - No Lead Solder (C)		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Lead (L)								
Copper - Lead Solder (CLS)		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)								
Galvanized (G)		Galvanized (G)					Galvanized (G)	Unknown (U)								
Lead (L)		Galvanized Requiring Replacemnt (GRR)					Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)								
Cast/Ductile Iron or Transite (O)		Lead (L)					Lead (L)									
Plastic - PVC, HDPE, PEX (P)		Cast/Ductile Iron or Transite (O)					Cast/Ductile Iron or Transite (O)									
Unknown (U)		Plastic - PVC, HDPE, PEX (P)					Plastic - PVC, HDPE, PEX (P)									
Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)														
		Unknown Not Lead (UNL)														
151 ABBEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
159 ABBEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
160 ABBEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
167 ABBEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
168 ABBEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
174 ABBEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
175 ABBEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1958 ABERDEEN CT/#1	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1958 ABERDEEN CT/#2	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1976 ABERDEEN CT/SUITE 1	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1976 ABERDEEN CT/SUITE 2	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1976 ABERDEEN CT/SUITE 3	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2025 ABERDEEN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
2060 ABERDEEN UNIT B/ UNIT C	n/a	N	Y			Visual Inspection	C	C	C	N/L		N/R	N			
2060 ABERDEEN CT/UNIT D	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1952 ABERDEEN CT	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2020 ABERDEEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2040 ABERDEEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2040 ABERDEEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2045 ABERDEEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2060 ABERDEEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2060 ABERDEEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1420 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1426 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1432 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1438 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1444 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1450 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1462 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1468 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1474 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1480 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1486 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1456 ADRIENNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1690 AFTON RD	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1709 AFTON RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1609 AFTON RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1629 AFTON RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1649 AFTON RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1650 AFTON RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1709 AFTON RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1710 AFTON RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1730 AFTON RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
435 AIRPORT RD	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
480 S AIRPORT RD	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
810 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
817 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
820 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
821 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
825 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
830 ALBERT AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
831 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
835 ALBERT AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
904 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
905 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
909 ALBERT AVE	LP1C020	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
910 ALBERT AVE	LA1C090	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
915 ALBERT AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
916 ALBERT AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
921 ALBERT AVE	n/a	N	Y			Visual Inspection	U	U	C	NL		N/R	N			
926 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
927 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
930 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
932 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
933 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
939 ALBERT AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
940 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
946 ALBERT AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1002 ALBERT AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1003 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1007 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1010 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1011 ALBERT AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1015 ALBERT AVE	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1016 ALBERT AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
242 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
344 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
115 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
116 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
123 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
124 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
209 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
210 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
218 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
226 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
233 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
234 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
311 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

328 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
343 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
413 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
414 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
421 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
422 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
429 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
430 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
437 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
438 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
445 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
446 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
502 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
503 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
510 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
511 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
518 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
519 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
526 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
527 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
534 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
542 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
604 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
612 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
628 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
702 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
710 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
718 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
726 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
805 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
806 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
813 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
814 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
821 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
829 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
837 ALDEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
845 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
853 ALDEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1071 ALEXANDRIA DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1073 ALEXANDRIA DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1075 ALEXANDRIA DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1077 ALEXANDRIA DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1101 ALEXANDRIA DR	n/a	N	N													

[illegible]

[illegible]

437 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
438 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		NR	N			
443 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
444 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
445 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
446 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
505 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
506 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
507 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
508 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
514 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
521 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
522 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
523 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
524 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
529 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
530 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
546 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
548 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
531 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
532 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
538 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
540 ANJALI CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
403 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
405 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
411 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
412 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
413 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
414 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
420 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
422 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
428 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
430 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
573 ANJALI CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
608 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
610 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
616 ANJALI CT	n/a	N	Y			Visual Inspection	C	C	C	NL		NR	N			
618 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
626 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
624 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
632 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
634 ANJALI CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
702 ANJALI CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N		</	

1161 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1167 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1175 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1178 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1181 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1184 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1187 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1190 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1193 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1196 ARBOR LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
613 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
617 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
622 ARCHIE PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
625 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
631 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
632 ARCHIE PL	LA1C148	N	Y	2024	2024	Exploratory dig	C	C	C	NL		2024	Y	2024		
642 ARCHIE PL	LA1C097	N	Y	unsure	unsure	Exploratory dig	C	C	C	NL		N/R	Y	unsure		
644 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
646 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
650 ARCHIE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1108 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1114 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1117 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1123 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1126 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1129 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1135 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1138 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1141 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1144 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1147 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1153 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1154 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1159 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1160 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1165 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1166 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1171 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1172 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1177 ARNEITA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1178 ARNEITA ST	n/a	N	N			Visual Inspection	C									

[illegible]

219 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
227 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
242 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
243 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
251 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
304 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
313 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
328 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 ASHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1915 ASTER RD	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1308 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1316 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1324 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1332 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1340 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1341 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1348 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1349 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1356 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1357 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1364 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1365 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1372 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1373 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1380 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1381 AXCEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
909 BAILEY RD	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
930 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1012 BAILEY RD	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1052 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
906 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
914 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
917 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
922 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
925 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
933																

1111 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1117 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1120 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1125 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1130 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1133 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1140 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1145 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1150 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1153 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1160 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1332 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1340 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1348 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1456 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1463 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1464 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1471 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1472 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1479 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1480 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1550 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1602 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1610 BAILEY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2030 BARON DR 101, 102, 103	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2030 BARON DR/#104	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2030 BARON DR/#105	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2030 BARON DR/106, 107, 108	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2030 BARON DR/#109, 110	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1603 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1611 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1612 BAYBERRY LN	LC4T044	N	N			Construction Records	C	C	C	NL		N/R	N			
1619 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1620 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1628 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1636 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1644 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1695 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1695 BAYBERRY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1418 BEACH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1426 BEACH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1435 BEACH LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1450 BEACH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1457 BEACH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
618 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
306 BECKER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
308 BECKER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
312 BECKER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
314 BECKER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
318 BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 BECKER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
326 BECKER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
330 BECKER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
332 BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
202 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
210 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
218 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
226 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
234 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
242 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

322 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
328 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
331 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
334 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
339 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
342 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
345 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
348 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
353 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
356 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
361 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
364 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
369 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
372 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
405 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
413 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
421 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
429 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
437 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
445 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
453 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
461 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
503 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
511 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
624 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
642 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
655 E BECKER PL	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
660 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
667 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
742 E BECKER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
864 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
871 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
872 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
880 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
888 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
891 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
910 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
918 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
921 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
926 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
929 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
934 BERKSHIRE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1625 BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1645 BETHANY RD	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
1675 BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1675 BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1675 BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1501 W BETHANY RD	LC4T028	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1519 W BETHANY RD	LC4T006	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1537 W BETHANY RD	LC4T037	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1555 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1573 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1591 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1675 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1701 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1947 W BETHANY RD	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1947 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2205 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2215 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2215 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2350 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2400 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2425 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2425 W BETHANY RD	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2433 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2435 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2439 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2445 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2475 W BETHANY RD	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2500 W BETHANY RD	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
2525 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2535 W BETHANY RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
515 BIRCH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
516 BIRCH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
524 BIRCH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
531 BIRCH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
532 BIRCH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
540 BIRCH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
805 BIRCHWOOD DR	LC4T045	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
815 BIRCHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
820 BIRCHWOOD DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
825 BIRCHWOOD DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
826 BIRCHWOOD DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
905 BIRCHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
908 BIRCHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
915 BIRCHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
918 BIRCHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
921 BIRCHWOOD DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
922 BIRCHWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
927 BIRCHWOOD DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1122 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 BORDEN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
325 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
331 BORDEN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
337 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
343 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
351 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
357 BORDEN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
417 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
420 BORDEN AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
420 BORDEN AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
427 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
437 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
439 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

441 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
643 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
645 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
651 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
653 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
705 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
707 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
820 BORDEN AVE	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
848 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
856 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
904 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
912 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
920 BORDEN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2311 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2319 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2327 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2335 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2343 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2419 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2422 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2427 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2430 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2435 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2438 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2446 BOYNTON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1504 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1505 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1506 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1507 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1508 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1509 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1510 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1511 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1512 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1513 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1515 BRADLEY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
354 BRANDON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
355 BRANDON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
363 BRANDON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
371 BRANDON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
703 BREMNER DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
705 BREMNER DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
707 BREMNER DR	n/a	N	N			Visual Inspection	C	C	C							

142 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
145 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
150 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
153 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
158 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
161 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
166 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
169 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
174 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
177 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
182 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
185 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
200 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
201 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
208 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
209 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
216 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
224 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
225 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
232 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
233 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
240 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
241 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
248 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
249 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
257 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
301 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
308 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
309 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
316 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
341 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
342 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
349 BRIAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
611 BRIAR DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
518 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
524 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
525 BRICKVILLE RD	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
545 BRICKVILLE RD	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
580 BRICKVILLE RD	n/a	N	Y			Visual Inspection										

1604 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1610 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1612 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1618 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1620 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1626 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1628 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1632 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1634 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1640 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1642 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1680 BRICKVILLE RD	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
615/617 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
627/629 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
639/641 BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
609 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
623 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
633 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
635 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
647 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
649 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
651 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1509 W BRICKVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2 BRIDEN LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
4 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
6 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
11 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
12 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
13 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
14 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
15 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
16 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
17 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
18 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
21 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
23 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
24 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
25 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
27 BRIDEN LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
38 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
42 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
47 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			

37 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
41 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
43 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
44 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
45 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
46 BRIDEN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
48 BRIDEN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
56 BRIDEN LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1742 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1745 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1750 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1753 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1758 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1761 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1766 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1769 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1774 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1777 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1782 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1785 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1790 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1793 BRIGGS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
557 BRIGHTON WAY	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
525 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
532 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
540 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
541 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
548 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
549 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
601 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
609 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
617 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
625 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
632 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
633 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
641 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
648 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
656 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
657 BRIGHTON WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1000 BRISTOL DR E	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1001 BRISTOL DR E	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1008 BRISTOL DR E	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1242 BRISTOL DR W	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1250 BRISTOL DR W	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1258 BRISTOL DR W	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1259 BRISTOL DR W	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1702 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1708 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1714 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1725 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1726 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1731 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1732 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1737 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1738 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1743 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1744 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1749 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1750 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1755 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1756 BROCK CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1702 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1708 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1711 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1714 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1719 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1720 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1726 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1727 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1732 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1735 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1738 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1743 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1744 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1751 BROOKHILL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1604 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1607 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1612 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1615 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1620 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1623 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1628 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1631 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1636 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1639 BROWER PL	n/a	N	N			Visual Inspection</										

1846 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1849 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1854 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1859 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1869 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1874 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1882 BROWER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
534 BUCKBOARD LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
536 BUCKBOARD LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
610 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
612 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
614 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
622 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
623 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
624 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
625 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
626 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
627 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
629 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
631 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
632 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
633 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
634 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
635 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
636 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
637 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
639 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
711 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
713 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
715 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
717 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
719 BUCKBOARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
890 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
892 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
894 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
896 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
900 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
901 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
902 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

932 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
933 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
934 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
935 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
936 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
937 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
940 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
941 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
942 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
943 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
944 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
945 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
946 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
947 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
950 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
951 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
952 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
953 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
954 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
955 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
956 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
957 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
960 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
962 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
964 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
966 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
970 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
971 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
972 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
973 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
974 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
975 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
976 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
977 BUCKINGHAM LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1760 C.L. HUDSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1763 C.L. HUDSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1768 C.L. HUDSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1773 C.L. HUDSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1776 C.L. HUDSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1781 C.L. HUDSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1784 C.L. HUDSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
421 N CALIFORNIA ST BLDG #10	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
121 N CALIFORNIA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
124 N CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
129 N CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 N CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
205 N CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
211 N CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
221 N CALIFORNIA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
227 N CALIFORNIA ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
304 N CALIFORNIA ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
309 N CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
314 N CALIFORNIA ST	LP1C004	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
321 N CALIFORNIA ST	LA1C083	N	Y	unsure	unsure	Exploratory dig	C	C	C	NL		N/R	Y	unsure		
328 N CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
321 N CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
329 N CALIFORNIA ST	LA1C084	N	N	2003	2003	Visual Inspection	C	C	C	NL		N/R	Y	2003		
332 N CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 N CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
338 N CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
357 N CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
412 N CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

421 N CALIFORNIA ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
449 N CALIFORNIA ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
516 N CALIFORNIA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
520 N CALIFORNIA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
522 N CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
114 S CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
117 S CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
120 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
121 S CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
123 S CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
124 1/2 S CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
124 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
128 S CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
204 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
205 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
209 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 S CALIFORNIA ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
216 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 S CALIFORNIA ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
220 S CALIFORNIA ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
223 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
303 S CALIFORNIA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
311 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 S CALIFORNIA ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
325 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
327 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
403 S CALIFORNIA ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
409 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
415 S CALIFORNIA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
416 S CALIFORNIA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
422 S CALIFORNIA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
423 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
428 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
433 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
434 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
437 S CALIFORNIA ST	LP1C021	N	N	unsure	unsure	Visual Inspection	C	C	C	NL		N/R	Y	unsure		
440 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
443 S CALIFORNIA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
443 1/2 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
448 S CALIFORNIA ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
456 S CALIFORNIA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
705 CAMBRIDGE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
710 CAMBRIDGE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
715 CAMBRIDGE PL	LC4T021	N	N			Visual Inspection	C	C	C	NL		N/R	N			
720 CAMBRIDGE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
725 CAMBRIDGE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
730 CAMBRIDGE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
735 CAMBRIDGE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1303 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1304 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1311 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1312 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1319 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1320 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1327 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1328 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1334 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1342 CAMDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
704 CAMERON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
712 CAMERON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
720 CAMERON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

728 CAMERON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
926 CAPITOL AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
864 CAPITOL AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
910 CAPITOL AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
918 CAPITOL AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
611 CARLSON ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
619 CARLSON ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
623 CARLSON ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
624 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
626 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
628 CARLSON ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
634 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
705 CARLSON ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
706 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
712 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
717 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
718 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
720 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
724 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
725 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
736 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
739 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
745 CARLSON ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
746 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
751 CARLSON ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
752 CARLSON ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
754 CARLSON ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
757 CARLSON ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1701 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1703 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1705 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1707 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1709 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1711 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1713 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1715 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1716 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1717 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1718 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1719 CEDARBROOK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1720 CEDARBROOK CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1721 CEDARBROOK CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1722 CEDARBROOK CT	n/a	N	N			Visual Inspection	C</									

2236 CELERITY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2243 CELERITY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2244 CELERITY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2321 CELERITY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2329 CELERITY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
CEMETERY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
503 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
504 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
507 CENTER AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
508 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
513 CENTER AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
514 CENTER AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
520 CENTER AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
520 1/2 CENTER AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
520 CENTER AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
521 CENTER AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
524 CENTER AVE	n/a	N	Y	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
525 CENTER AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
530 CENTER AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
533 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
536 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
537 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
543 CENTER AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
544 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
549 CENTER AVE	n/a	N	Y	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
550 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
554 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
559 CENTER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
111 CENTER CROSS ST	LP1C018	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
117 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
118 CENTER CROSS ST	LA3R114	N	N	1998	1998	Construction Records	C	C	C	NL		N/R	Y	1998		
123 CENTER CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
124 CENTER CROSS ST	n/a	N	Y	2024	2024	Visual Inspection	P	P	C	NL		N/R	Y	2024		
125 CENTER CROSS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
130 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
133 CENTER CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
140 CENTER CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
141 CENTER CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
203 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
206 CENTER CROSS ST	LA3R117	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
209 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
216 CENTER CROSS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
223 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
226 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
227 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
233 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
236 CENTER CROSS ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
303 CENTER CROSS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
309 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
315 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
327 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
406 CENTER CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
412 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
416 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
503 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
506 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
508 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
515 CENTER CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
516 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
525 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

531 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
537 CENTER CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1807 CHARLES KELLUM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1817 CHARLES KELLUM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1827 CHARLES KELLUM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			4/29/2024
218 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
224 CHARLES ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
229 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 CHARLES ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
234 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
239 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
240 CHARLES ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
243 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
246 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
248 CHARLES ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
251 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
252 CHARLES ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
266 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
268 CHARLES ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
307 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
309 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
315 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
316 CHARLES ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
324 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
333 CHARLES ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
334 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 CHARLES ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
340 CHARLES ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
401 CHARLES ST	LP1C012	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
404 CHARLES ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
407 CHARLES ST	LA1C129	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
410 CHARLES ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
417 CHARLES ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
420 CHARLES ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
425 CHARLES ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
426 CHARLES ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
431 CHARLES ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
501 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
502 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
508 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
508 1/2 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
509 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
510 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
512 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
517 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
521 CHARLES ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
525 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
528 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
536 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
601 CHARLES ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
609 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
613 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
621 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
629 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
635 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
645 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
651 CHARLES ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
705 CHARLES ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1754 CHARLES WAITE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1757 CHARLES WAITE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

564 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
565 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
566 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
567 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
580 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
581 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
582 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
583 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
584 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
585 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
586 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
587 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
600 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
601 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
602 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
603 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
604 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
605 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
606 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
607 CLAYTON CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 CLOVERLANE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
325 CLOVERLANE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
475 CLOVERLANE DR.	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
476 CLOVERLANE DR	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
520 E CLOVERLANE	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
328 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
341 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
349 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
420 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
428 CLOVERLANE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
435 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
436 CLOVERLANE DR	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
445 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
465 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
530 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
531 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
540 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
541 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
608 E CLOVERLANE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
609 E CLOVERLANE DR	n/a															

2030 COLTONVILLE RD	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2040 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2042 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2044 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2046 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2048 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2050 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2052 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2054 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2054 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2056 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2058 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2060 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2190 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2198 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2212 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2222 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2228 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2238 COLTONVILLE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1004 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1005 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1007 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1008 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1009 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1012 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1014 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1017 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1018 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1021 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1024 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1025 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1028 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1032 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1033 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1034 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1038 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1039 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1043 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1044 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1047 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1104 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1105 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1107 COMMERCIAL ST	n/a	N	Y	2023	2023											

1224 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1225 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1227 COMMERCIAL ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1233 COMMERCIAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2207 CONCORD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2209 CONCORD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2215 CONCORD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2217 CONCORD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2223 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2225 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2231 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2233 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2239 CONCORD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2241 CONCORD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2390 CONCORD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2200 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2202 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2204 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2206 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2208 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2210 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2214 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2216 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2218 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2220 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2222 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2224 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2234 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2236 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2238 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2240 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2242 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2244 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2246 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2300 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2302 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2304 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2306 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2308 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2310 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2311 CONCORD DR	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
2312 CONCORD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2313 CONCORD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			

302 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
303 CONLIN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
314 CONLIN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
315 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
322 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
323 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 CONLIN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
340 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
341 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
348 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
349 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
356 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
357 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
365 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
409 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
423 CONLIN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
424 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
507 CONLIN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
508 CONLIN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
509 CONLIN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
510 CONLIN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
803 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
805 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
807 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
809 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
813 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
815 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
817 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
819 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
823 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
825 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
827 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
829 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
833 CONSTANCE LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
835 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
837 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
839 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
939 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
941 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
943 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
945 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
950 CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
952 CONSTANCE LN	n/a	N</														

965A CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
965B CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
965C CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
965D CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
965E CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
965F CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
965G CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
965H CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
973A CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
973B CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
973C CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
973D CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
973E CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
973F CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
981A CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
981B CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
981C CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
981D CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
981E CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
981F CONSTANCE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1815 CONSTITUTION ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1831 CONSTITUTION ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1839 CONSTITUTION ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1847 CONSTITUTION ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1909 CONSTITUTION ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1917 CONSTITUTION ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1925 CONSTITUTION ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1933 CONSTITUTION ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1203 COOLIDGE CT	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
1210 COOLIDGE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1211 COOLIDGE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1218 COOLIDGE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1219 COOLIDGE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1226 COOLIDGE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
405 COTTAGE ROW	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
406 COTTAGE ROW	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
412 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
413 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
417 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
422 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
426 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
430 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
506 COTTAGE ROW	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
604 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 COTTAGE ROW	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
615 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 COTTAGE ROW	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
619 COTTAGE ROW	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 A COTTAGE ROW	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
620 B COTTAGE ROW	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
801 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
807 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
813 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
819 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
825 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
831 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
832 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
837 COVENTRY CIR N	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
840 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
843 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
848 COVENTRY CIR N	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
849 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

855 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
856 COVENTRY CIR N	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
861 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
867 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
873 COVENTRY CIR N	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
879 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
885 COVENTRY CIR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2241 COVENTRY CIR S	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
804 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2221 COVENTRY CIR S	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2230 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2231 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2240 COVENTRY CIR S	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2251 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2260 COVENTRY CIR S	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2261 COVENTRY CIR S	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2271 COVENTRY CIR S	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2307 COVENTRY CIR S	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2313 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2319 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2320 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2325 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2330 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2331 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2337 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2340 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2343 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2349 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2350 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2355 COVENTRY CIR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 CRESCENT DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
311 CRESCENT DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
312 CRESCENT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 CRESCENT DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
318 CRESCENT DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
323 CRESCENT DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
324 CRESCENT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 CRESCENT DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
332 CRESCENT DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
335 CRESCENT DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
336 CRESCENT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
341 CRESCENT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
346 CRESCENT DR	n/a	N	Y			Visual Inspection</										

832 CROATIAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
837 CROATIAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
838 CROATIAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
843 CROATIAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
849 CROATIAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
850 CROATIAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
856 CROATIAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
862 CROATIAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
917 CROSBY AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
917 CROSBY AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
917 CROSBY AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
917 CROSBY AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
978 CROSBY AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
986 CROSBY AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
994 CROSBY AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1002 CROSBY AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1018 CROSBY AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #101	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #102	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #103	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #104	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #105	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #106	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #107	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #108	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #109	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/UTILITY BLDG	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #202	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #203	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #204	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #205	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #206	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #207	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #208	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #209	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #211	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #212	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #213	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #214	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
117 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
122 N CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
127 N CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
129 N CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
137 N CROSS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
143 N CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
144 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
149 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
150 N CROSS ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
160 N CROSS ST	LA1C078	N	N	unsure	unsure	Visual Inspection	C	C	C	NL		N/R	Y	unsure		
203 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
206 N CROSS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
211 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
212 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
216 N CROSS ST	LA1C077	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
221 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
227 N CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
228 N CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
233 N CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
236 N CROSS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
239 N CROSS ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
246 N CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
247 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

249 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
251 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
252 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
253 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
254 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
258 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
260 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
266 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
268 N CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
276 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 N CROSS ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
355 N CROSS ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
370 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
390 N CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
475 N CROSS ST	n/a	N	N	2022	2022	Construction Records	O	O	O	NL		N/R	Y	2022		
501 N CROSS ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
275 N CROSS ST/APT #110	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #201	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #215	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #216	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
275 N CROSS ST/APT #210	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 DAHL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
225 DAHL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 DAHL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 DAHL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
240 DAHL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1113 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1119 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1125 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1253 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1265 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1501 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1507 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1510 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1513 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1516 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1519 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1522 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1525 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1528 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1531 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1534 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1537 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1540 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1543 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1549 DANIEL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1131 DANIEL DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1137 DANIEL DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1143 DANIEL DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1235 DANIEL DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1241 DANIEL DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1247 DANIEL DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1259 DANIEL DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1220 DARLING CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1227 DARLING CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1228 DARLING CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1235 DARLING CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1236 DARLING CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1243 DARLING CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1244 DARLING CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1326 DAVID DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1320 DAVID DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1322 DAVID DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1323 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1324 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1325 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1327 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1329 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1408 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1410 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1412 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1418 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1420 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1422 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1428 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1430 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1432 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1438 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1440 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1442 DAVID DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
133 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
141 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
149 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
157 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
165 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
205 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
206 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
213 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
214 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
221 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
222 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
229 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
309 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
318 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
433 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
441 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
444 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
449 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
452 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
457 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
460 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
465 DAVIS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
326 DAVIS ST	n/a	N	N													

2429 DEAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2436 DEAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2437 DEAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2444 DEAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2445 DEAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2453 DEAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2461 DEAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
440 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#101/102	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#103	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#104A	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#105	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#106	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#107-108	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#110	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#109	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#111	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 DEKALB AVE/#104	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1840 DEKALB AVE SUITE 2	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
440 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
448 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
513 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
535 DEKALB AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
560 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
603 DEKALB AVE	LA1C136	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
611 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
614 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
617 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
619 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
624 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
625 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
631 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
633 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
705 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
706 DEKALB AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
714 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
715 DEKALB AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
720 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
727 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
728 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
733 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
736 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
741 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
806 DEKALB AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
816 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
821 DEKALB AVE	LP1C002	N	N	2001	2001	Construction Records	C	C	C	NL		N/R	Y	2001		
822 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
825 DEKALB AVE	LP1C014	N	N	2001	2001	Construction Records	C	C	C	NL		N/R	Y	2001		
829 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
832 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
837 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
840 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
843 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
848 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
849 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
852 DEKALB AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
859 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
860 DEKALB AVE	LA1C146	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
863 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
868 DEKALB AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		

1670 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1690 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1700 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1709 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1710 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1711 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1715 DEKALB AVE	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
1715 DEKALB AVE	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
1715 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1719 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1735 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1745 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1760 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1775 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1780 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1780 DEKALB AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1801 DEKALB AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1810 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1825 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1825 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1840 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1840 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1860 DEKALB AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1875 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1925 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1935 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1940 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1950 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1950 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1955 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1957 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1985 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1985 DEKALB AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
2001 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2496 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2496 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2496 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2570 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2580 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2600 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2600 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2600 DEKALB AVE	n/a	N	N			Visual Inspection	C	C	C	NL						

[illegible]

170 DONLIN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
2820 DOSEN DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
2307 DUSTIN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2312 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2317 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2320 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2327 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2328 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2336 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2337 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2344 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2415 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2420 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2423 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2428 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2431 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2436 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2439 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2447 DUSTIN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2105 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2110 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2111 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2117 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2118 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2126 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2127 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2134 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2135 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2142 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2144 EASTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
595 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
601 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
607 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
613 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
619 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
622 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
625 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
628 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
631 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
634 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
637 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
640 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
643 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
646 EASY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2315 EDGEBROOK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
225 EDWARD ST	n/a	Y	Y			Construction Records	O	O	O	NL		N/R	N			
228 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
232 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
239 EDWARD ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
240 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
250 EDWARD ST	LA1C127	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
254/256 EDWARD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
267 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
309 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
310 EDWARD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
317 EDWARD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
326 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
335 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			

335 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
335 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
336 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 EDWARD ST	LA1C075	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
344 1/2 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
355 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
403 EDWARD ST	LA1C094	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
407 EDWARD ST	LP1C022	N	N	2012	2012	Construction Records	C	C	C	NL		N/R	Y	2012		
410 EDWARD ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		NR	Y	2024		
415 EDWARD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
416 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
423 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
424 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
431 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 EDWARD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
437 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
440 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
447 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
448 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
502 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
503 EDWARD ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
508 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
509 EDWARD ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
515 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
516 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
518 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
521 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
524 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
525 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
602 EDWARD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
605 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
606 EDWARD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
609 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 EDWARD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
614 EDWARD ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
617 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
622 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
623 EDWARD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
628 EDWARD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
631 EDWARD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
638 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
639 EDWARD ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
644 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
645 EDWARD ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
650 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
653 EDWARD ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
659 EDWARD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
704 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
708 EDWARD ST	LA1C069	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
712 EDWARD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
716 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
717 EDWARD ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
722 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
725 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
731 EDWARD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
736 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
739 EDWARD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1508 ELECTRIC PARK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1530 ELECTRIC PARK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1615 ELECTRIC PARK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1625 ELECTRIC PARK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1705 ELECTRIC PARK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

321 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
328 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
345 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
352 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
353 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
360 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
361 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
368 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
369 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
374 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
377 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
382 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
390 ELI BARNES CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
308 ELI G JEWELL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
316 ELI G JEWELL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 ELI G JEWELL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
340 ELI G JEWELL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
348 ELI G JEWELL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 ELI G. JEWELL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
356 ELI G. JEWELL CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1804 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1810 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1816 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1821 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1822 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1827 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1828 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1833 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1834 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1839 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1845 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1851 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1857 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1863 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1869 ELIZABETH CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
211 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
221 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
223 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
225 ELLEN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
231 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
241 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
251 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
257 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
259 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
267 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
273 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
279 ELLEN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1710 ELLSWORTH DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
403 W ELM	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
114 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 E ELM ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
141 E ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
203 E ELM ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
204 E ELM ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
211 E ELM ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		

214 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
218 E ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
221 E ELM ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
222 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
227 E ELM ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
230 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
303 E ELM ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
313 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
314 E ELM ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
319 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
328 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
405 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
410 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
411 E ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
414 E ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
417 E ELM ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
420 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
426/428 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
427 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 E ELM ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
437 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
438 E ELM ST	LA1C128	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
450 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
451 E ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
456 E ELM ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
459 E ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
466 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
467 E ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
472 E ELM ST	LA1C092	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
473 E ELM ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
478 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
483 E ELM ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
484 E ELM ST	n/a	N	Y			Visual Inspection	L	C	C	NL		N/R	N			
490 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
491 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
493 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
496 E ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
111 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
112 W ELM ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
120 W ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
124 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
126 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
131 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
131 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
204 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
206 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
211 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
315 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 W ELM ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
406 W ELM ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
412 W ELM ST	LC1T005	N	N			Visual Inspection	C	C	L	L		5/7/24	N		Yes	6/12/2023
413 W ELM ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
475 W ELM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
510 ELMWOOD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
515 ELMWOOD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
521 ELMWOOD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
526 ELMWOOD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		

527 ELMWOOD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
533 ELMWOOD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
603 ELMWOOD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
607 ELMWOOD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
662 ELMWOOD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
706 ELMWOOD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
711 ELMWOOD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
714 ELMWOOD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
607 EMANUEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
619 EMANUEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
648 EMANUEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
724 EMANUEL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
604 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
606 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
607 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
612 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
615 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
626 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
627 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
633 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
634 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
639 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
640 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
645 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
648 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
653 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
654 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
661 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
662 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
669 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
703 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
704 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
711 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
712 EMMERT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1000 EMMSSEN DR/#1	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1000 EMMSSEN DR/#3	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1000 EMMSSEN DR/#5	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1000 EMMSSEN DR/OUTSIDE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1000 EMMSSEN DR/#2	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1000 EMMSSEN DR/#4	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1000 EMMSSEN DR/#6	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1013 EMMSSEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1020 EMMSSEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1021 EMMSSEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1022 EMMSSEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1023 EMMSSEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1028 EMMSSEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1030 EMMSSEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
806 ESTHER AVE	n/a	N	Y			Visual Inspection	L	C	C	NL		N/R	N			
811 ESTHER AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
815 ESTHER AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
820 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
823 ESTHER AVE	LCST083	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
824 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
830 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
831 ESTHER AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
834 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
904 ESTHER AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
907 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
908 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

913 ESTHER AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
914 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
918 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
919 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
922 ESTHER AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
925 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
930 ESTHER AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
932 ESTHER AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
933 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
937 ESTHER AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1303 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1311 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1319 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1327 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1334 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1335 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1343 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1351 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1352 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1359 EVERETT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
180 E EXCHANGE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
230 E EXCHANGE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
303 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 E EXCHANGE ST	LA1C085	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
315 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 E EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
327 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
407 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
411 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
413 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
421 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
429 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
430 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
433 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
434 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
436 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
440 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
442 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
447 E EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
448 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
450 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
452 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
453 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
454 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
458 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
459 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
460 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
462 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
464 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
465 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
466 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
468 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
471 E EXCHANGE ST	LP1C013	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
476 E EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
480 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
481 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
485 E EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
486 E EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
493 E EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		

494 E EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
107 W EXCHANGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
115 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
119 W EXCHANGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
123 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
127 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
129 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
209 W EXCHANGE ST	LA1C142	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
210-228 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
213 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
217 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
225 W EXCHANGE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
233 W EXCHANGE ST	LA1C073	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
239 W EXCHANGE ST	LA1C080	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
240 W EXCHANGE ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
245 W EXCHANGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
305 W EXCHANGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
313 W EXCHANGE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
321 W EXCHANGE ST	LA1C098	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
322 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
330 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
334 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
340 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
341 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
403 W EXCHANGE ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
419 W EXCHANGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
421 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
427 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
432 W EXCHANGE ST	LA1C120	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
433 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
438 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
441 W EXCHANGE ST	LA1C138	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
444 W EXCHANGE ST	LA1C118	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
445 W EXCHANGE ST	LA1C119	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
451 W EXCHANGE ST	LA1C121	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
452 W EXCHANGE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
462 W EXCHANGE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
463 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
468 W EXCHANGE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
469 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
474 W EXCHANGE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
475 W EXCHANGE ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
476 W EXCHANGE ST	LC1T001	N	Y			Visual Inspection	L	L	L	L		5/7/24	N		Yes	4/29/2024
500 W EXCHANGE ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
503 W EXCHANGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
510 W EXCHANGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
538 W EXCHANGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1323 FABIEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1348 FABIEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1351 FABIEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1301 FABIEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1302 FABIEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1310 FABIEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1315 FABIEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1326 FABIEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1331 FABIEN DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1339 FABIEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1342 FABIEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1354 FABIEN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
115 FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
121 FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
125 FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
133 FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
139 FAIR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
145 FAIR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
205 FAIR ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
213 FAIR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 FAIR ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
240 FAIR ST	n/a	Y	Y			Construction Records	O	O	O	NL		N/R	N			
263 FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
275 FAIR ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
304 FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
307 FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
312 FAIR ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
315 FAIR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
318 FAIR ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
326 FAIR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
406 FAIR ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
410 FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
411 FAIR ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
415 FAIR ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
418 FAIR ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
423 FAIR ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
424 FAIR ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
429 FAIR ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
430 FAIR ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
436 FAIR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
511 FAIR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 N FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
138 N FAIR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
204 N FAIR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
2104 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2105 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2110 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2111 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2117 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2118 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2123 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2126 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2129 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2134 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2135 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2140 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2141 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2142 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2147 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2203 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2213 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2214 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2218 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2221 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2231 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2304 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2308 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2309 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2319 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2320 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2322 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2406 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2408 FAIRLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

421 FAIRWAY LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
429 FAIRWAY LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
525 FAIRWAY LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
413 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
453 FAIRWAY LN	n/a	N	Y			Visual Inspection	C	P	C	NL		N/R	N			
530 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
533 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
540 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
541 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
550 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
619 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
631 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
640 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
710 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
720 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
730 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
740 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
750 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
755 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
760 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
765 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
765 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
770 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
785 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
795 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
805 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
810 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
815 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
825 FAIRWAY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1831 FORD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1848 FORD ST	n/a		N			Visual Inspection	C	C	C	NL		NR	N			
1909 FORD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1917 FORD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1925 FORD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1933 FORD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1941 FORD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 FOX AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
675 FOX AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
706 FOX AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
722 FOX AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1313 FOXBEND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1314 FOXBEND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1322 FOXBEND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1329 FOXBEND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1330 FOXBEND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1337 FOXBEND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1338 FOXBEND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
755 FOXOINTE DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
720 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
725 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
760 FOXPOINTE DR	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
760 FOXPOINTE DR	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
845 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
847 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
849 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
851 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
905 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
907 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
909 FOXPOINTE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

703 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
711 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
719 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
727 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1103 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1120 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1128 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1136 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1204 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1510 FREED RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
918 FREEDOM CIR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
918 FREEDOM CIR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1164 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
910 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
915 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
926 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
934 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
935 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
942 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1012 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1019 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1020 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1035 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1036 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1145 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1148 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1156 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1161 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1164 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1169 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1245 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1246 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1265 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1318 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1326 FREEDOM CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1540 FULTON LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1614 FULTON LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1622 FULTON LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1630 FULTON LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1638 FULTON LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1720 FULTON LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1728 FULTON LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1736 FULTON LN	n/a	N	N			Visual Inspection	C	C	C							

339 GARDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
340 GARDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
347 GARDEN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
348 GARDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
353 GARDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
354 GARDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
359 GARDEN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
360 GARDEN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1630 GATEWAY DR/1	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
1850 GATEWAY DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1850 GATEWAY DR	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2185 GATEWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2200 GATEWAY DR	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2225 GATEWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2225 GATEWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2245 GATEWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
304 GEORGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
305 GEORGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
311 GEORGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 GEORGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 GEORGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
318 GEORGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 GEORGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
330 GEORGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 GEORGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 GEORGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
342 GEORGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
347 GEORGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 GEORGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
303 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
306 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
311 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
320 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
331 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
332 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
337 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
338 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
339 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
405 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
406 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
411 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
414 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
419 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
422 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
425/427 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
431/433 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
501/503 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
507 GEORJEAN CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
513 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
514 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
515 GEORJEAN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1604 GINGERCREEK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1606 GINGERCREEK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1610 GINGERCREEK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1612 GINGERCREEK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1614 GINGERCREEK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1616 GINGERCREEK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1618 GINGERCREEK CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1291 GRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1293 GRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1295 GRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1297 GRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 1/2 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
311 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
316 GRANT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
317 GRANT ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
320 GRANT ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
321 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
326 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
326 1/2 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 GRANT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
338 GRANT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
343 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 GRANT ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
351 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
355 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
361 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
365 GRANT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
404 GRANT ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
405 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
408 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
412 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
418 GRANT ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
422 GRANT ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
504 GRANT ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
505 GRANT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
510 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
511 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
515 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
519 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
520 GRANT ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
524 GRANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
116 GREELEY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
124 GREELEY ST	LP3S010	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 GREELEY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
140 GREELEY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1038 GREENLEAF ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1153 GREENLEAF ST	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
818 GREENLEAF ST	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
845 GREENLEAF ST	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
926 GREENLEAF ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
934 GREENLEAF ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
942 GREENLEAF ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
943 GREENLEAF ST	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
1022 GREENLEAF ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1030 GREENLEAF ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
607 GREENLEAF ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
608 GREENLEAF ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 GREENLEAF ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
617 GREENLEAF ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
407 HADLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
412 HADLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
413 HADLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
418 HADLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
901 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
909 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
914 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
917 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

922 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
930 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
937 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
940 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
943 HAMILTON DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
949 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
955 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
958 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
961 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
967 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
968 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
973 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
979 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
980 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
985 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
998 HAMILTON DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1201 HATHAWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1203 HATHAWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1205 HATHAWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1207 HATHAWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1211 HATHAWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1213 HATHAWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1215 HATHAWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1217 HATHAWAY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2530 HAUSER ROSS DR/#100	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2540 HAUSER ROSS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2540 HAUSER ROSS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2540 HAUSER ROSS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2540 HAUSER ROSS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2550 HAUSER ROSS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2550 HAUSER ROSS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2560 HAUSER ROSS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2560 HAUSER ROSS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
10 HEALTH SERVICES DR	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
12 HEALTH SERVICES DR	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
14 HEALTH SERVICES DR	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
1125 HERON CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
938 HERON CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
946 HERON CREEK DR	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
954 HERON CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
962 HERON CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1102 HERON CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1110 HERON CREEK DR	n/a	N	N			Visual Inspection	C									

121 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
122 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
127 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
205 W HIGH ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
313 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
322 W HIGH ST	LA1C125	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
328 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
405 W HIGH ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
411 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
412 W HIGH ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
418 W HIGH ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
419 W HIGH ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
419 1/2 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
421 W HIGH ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
423 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
428 W HIGH ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
432 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
433 W HIGH ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
441 W HIGH ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
441 W HIGH ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
2111 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2112 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2119 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2120 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2127 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2128 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2135 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2136 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2143 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2144 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2152 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2200 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2206 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2207 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2214 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2219 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2220 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2226 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2304 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2307 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2309 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2311 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2312 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2316 HIGHLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
611 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
639 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
641 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
642 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
647 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
649 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
650 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
652 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
655 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
657 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
658 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
660 HILL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
806 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
807 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
815 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
822 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

823 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
830 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
836 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
844 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
852 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
860 HILLCREST AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
115 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 HOME ST	LA1C137	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
121 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
128 HOME ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
204 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
206 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
211 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
222 HOME ST	LA1C147	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
230 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
304 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
308 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
315 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
316 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 HOME ST	LP1C023	N	N	1999	1999	Visual Inspection	C	C	C	NL		N/R	Y	1999		
324 HOME ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
331 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
334 HOME ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
341 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
349 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
356 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
360 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
360 1/2 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
361 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
363 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
366 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
374 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
380 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
387 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
388 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
394 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
400 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
404 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
405 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
410 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
415 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
418 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
421 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
425 HOME ST	LA1C074	N	Y	unsure	unsure	Visual Inspection	C	C	C	NL		N/R	Y	unsure		
430 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
433 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
504 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
505 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
514 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
515 HOME ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
520 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
526 HOME ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
535 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
536 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
543 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
544 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
551 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
552 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
604 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

605 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
612 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
613 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
628 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
629 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
636 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
641 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
644 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
710 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
718 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
726 INDEPENDENCE AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
735 INDEPENDENCE AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1704 IRONWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1710 IRONWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1713 IRONWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1716 IRONWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1722 IRONWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1728 IRONWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
623 IVAN DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
665 IVAN DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
653 IVAN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1836 J.C. KELLOG ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
138 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
139 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
146 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
147 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
154 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
155 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
162 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
163 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
170 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
171 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
178 JACKSON BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
423 JAMI DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
428 JAMI DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
800 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
805 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
808 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
816 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
902 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1318 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1319 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1326 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1327 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1334 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1335 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1342 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1343 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1350 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1351 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1358 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1366 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1400 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1408 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1409 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1416 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1417 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1424 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1425 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1432 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1433 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1440 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1441 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1448 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1449 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1456 JANET ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1835 JC KELLOGG ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1815 JC KELLOG ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1816 JC KELLOG ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1825 JC KELLOG ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1826 JC KELLOG ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1102 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1103 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1112 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1113 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1122 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1123 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1152 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1153 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1162 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1163 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1172 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1173 JENNY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

1567 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1572 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1575 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1580 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1588 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1603 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1611 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1619 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1627 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1635 JOHN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
160 JOHNSON AVE	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
1636 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1644 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1652 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1760 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1768 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1776 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1784 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1792 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1811 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1812 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1819 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1820 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1826 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1827 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1832 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1835 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1838 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1844 JOSEPH SIXBURY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1250 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1256 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1261 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1262 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1267 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1268 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1273 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1274 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1279 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1280 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1290 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1296 JOSIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
427 JOY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
430 JOY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 JOY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
908 JUNIPER DR	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
1020 JUNIPER DR	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
1028 JUNIPER DR	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
1012 JUNIPER DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1036 JUNIPER DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1052 JUNIPER DR	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
1136 JUNIPER DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1112 JUNIPER DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1117 JUNIPER DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1125 JUNIPER DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1128 JUNIPER DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1133 JUNIPER DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1141 JUNIPER DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1060 JUNIPER DR	n/a	N				Visual Inspection	P	C	P	NL		N/R	N			
1149 JUNIPER DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1611 KAYLEE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1612 KAYLEE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1617 KAYLEE CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

5 KISHWAUKEE HOSPITAL DR	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
847 KRPAN DR	LC4T046	N	N			Construction Records	C	C	C	NL		N/R	N			
854 KRPAN DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
855 KRPAN DR	LC4T047	N	N			Construction Records	C	C	C	NL		N/R	N			
862 KRPAN DR	LC4T048	N	N			Construction Records	C	C	C	NL		N/R	N			
863 KRPAN DR	LC4T042	N	N			Construction Records	C	C	C	NL		N/R	N			
870 KRPAN DR	LC4T049	N	N			Construction Records	C	C	C	NL		N/R	N			
871 KRPAN DR	LC4T050	N	N			Construction Records	C	C	C	NL		N/R	N			
902 KRPAN DR	LC4T051	N	N			Construction Records	C	C	C	NL		N/R	N			
903 KRPAN DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
910 KRPAN DR	LC4T052	N	N			Construction Records	C	C	C	NL		N/R	N			
911 KRPAN DR	LC4T053	N	N			Construction Records	C	C	C	NL		N/R	N			
918 KRPAN DR	LC4T054	N	N			Construction Records	C	C	C	NL		N/R	N			
919 KRPAN DR	LC4T055	N	N			Construction Records	C	C	C	NL		N/R	N			
926 KRPAN DR	LC4T016	N	N			Construction Records	C	C	C	NL		N/R	N			
927 KRPAN DR	LC4T056	N	N			Construction Records	C	C	C	NL		N/R	N			
934 KRPAN DR	LC4T057	N	N			Construction Records	C	C	C	NL		N/R	N			
935 KRPAN DR	LC4T058	N	N			Construction Records	C	C	C	NL		N/R	N			
942 KRPAN DR	LC4T031	N	N			Construction Records	C	C	C	NL		N/R	N			
943 KRPAN DR	LC4T059	N	N			Construction Records	C	C	C	NL		N/R	N			
1004 KRPAN DR	LC4T034	N	N			Construction Records	C	C	C	NL		N/R	N			
1005 KRPAN DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1012 KRPAN DR	LC4T035	N	N			Construction Records	C	C	C	NL		N/R	N			
1013 KRPAN DR	LC4T039	N	N			Construction Records	C	C	C	NL		N/R	N			
1020 KRPAN DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1021 KRPAN DR	LC4T060	N	N			Construction Records	C	C	C	NL		N/R	N			
1151 LAMOIS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1159 LAMOIS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1167 LAMOIS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1260 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1301 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1302 LARSON ST	LC4T025	N	N			Construction Records	C	C	C	NL		N/R	N			
1309 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1310 LARSON ST	LC4T022	N	N			Construction Records	C	C	C	NL		N/R	N			
1317 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1318 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1325 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1326 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1333 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1334 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1341 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1342 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1349 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1350 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1357 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1404 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1411 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1412 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1419 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1420 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1427 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1428 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1435 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1436 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1443 LARSON ST	LC4T013	N	N			Construction Records	C	C	C	NL		N/R	N			
1444 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1451 LARSON ST	LC4T061	N	N			Construction Records	C	C	C	NL		N/R	N			
1452 LARSON ST	LC4T062	N	N			Construction Records	C	C	C	NL		N/R	N			
1459 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1460 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1503 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1508 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			

1511 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1516 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1519 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1524 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1527 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1532 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1535 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1540 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1543 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1548 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1551 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1556 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1559 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1564 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1572 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1580 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1600 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1608 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1611 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1616 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1624 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1632 LARSON ST	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
203 LEAH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
204 LEAH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
211 LEAH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
214 LEAH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 LEAH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
224 LEAH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
227 LEAH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
234 LEAH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1801 LETHA WESTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1804 LETHA WESTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1811 LETHA WESTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1814 LETHA WESTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1821 LETHA WESTGATE DR	n/a		N			Visual Inspection	C	C	C	NL		NR	N			
1824 LETHA WESTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1841 LETHA WESTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1851 LETHA WESTGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
105 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
125 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
135 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
140 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
145 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
150 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
155 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
160 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
170 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
175 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
180 LIBERTY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
111 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
122 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
123 E LINCOLN ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
128 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
205 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
216 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
221 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
224 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
225 E LINCOLN ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
229 E LINCOLN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		

230 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
236 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
306 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
312 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
315 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
319 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
320 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
325 E LINCOLN ST	LP3S055	N	N			Construction Records	C	C	C	NL		N/R	N			
326 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
331 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
338 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
345 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
346 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
349 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
352 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
357 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
358 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
363 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
364 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
367 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
370 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
373 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
378 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
379 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
384 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
385 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
390 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
395 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
398 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
401 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
404 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
407 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
410 E LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
413 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
416 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
419 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
422 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
428 E LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
108 W LINCOLN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
112 W LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
116 W LINCOLN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
117 W LINCOLN ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
120 W LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
121 W LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
124 W LINCOLN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
132 W LINCOLN ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
430 LINCOLNSHIRE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
435 LINCOLNSHIRE DR	LC4T063	N	N			Construction Records	C	C	C	NL		N/R	N			
440 LINCOLNSHIRE DR	LC4T064	N	N			Construction Records	C	C	C	NL		N/R	N			
445 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
450 LINCOLNSHIRE DR	LC4T011	N	N			Construction Records	C	C	C	NL		N/R	N			
455 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
465 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
470 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
475 LINCOLNSHIRE DR	LC4T032	N	N			Construction Records	C	C	C	NL		N/R	N			
485 LINCOLNSHIRE DR	LC4T065	N	N			Construction Records	C	C	C	NL		N/R	N			
490 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
491 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
501 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			

509 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
516 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
517 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
524 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
525 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
532 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
535 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
540 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
541 LINCOLNSHIRE DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
2306 LINDLEY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2314 LINDLEY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2322 LINDLEY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2330 LINDLEY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
229 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
304 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
313 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 N LOCUST ST	LA1C153	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
320 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 N LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
327 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 1/2 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 N LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
340 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
347 N LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
350 N LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
351 N LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
314/316 N LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
122 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 S LOCUST ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
226 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
228 1/2 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
228 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
229 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
313 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 S LOCUST ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
322 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
406 S LOCUST ST	LP1C005	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
414 1/2 S LOCUST ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
414 S LOCUST ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
415 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
421 S LOCUST ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
422 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
428 S LOCUST ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
429 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
512 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
513 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
517 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
523 S LOCUST ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
529 S LOCUST ST	LA1C126	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
609 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
614 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
615 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
718 S LOCUST ST	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
821 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
828 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
916 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
917 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
924 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			

925 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
932 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
933 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
940 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
941 S LOCUST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
943 S LOCUST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1004 LONDON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1012 LONDON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1013 LONDON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1020 LONDON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1021 LONDON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1028 LONDON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1465 LONGWOOD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1465 LONGWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1467 LONGWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1469 LONGWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1471 LONGWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1473 LONGWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1475 LONGWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1477 LONGWOOD DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1479 LONGWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1501 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1501 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1503 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1505 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1507 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1509 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1511 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1513 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1515 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1551 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1601 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1602 LONGWOOD DR	LC4T030	N	N			Construction Records	C	C	C	NL		N/R	N			
1605 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1608 LONGWOOD DR	LC4T033	N	N			Construction Records	C	C	C	NL		N/R	N			
1609 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1614 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1617 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1620 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1626 LONGWOOD DR	LC4T066	N	N			Construction Records	C	C	C	NL		N/R	N			
1705 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1706 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1711 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1713 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1715 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1717 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1720 LONGWOOD DR	LC4T067	N	N			Construction Records	C	C	C	NL		N/R	N			
1770 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1771 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1772 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1773 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1775 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1777 LONGWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
618 LOOMIS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
619 LOOMIS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 LOOMIS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
625 LOOMIS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
218 LUCAS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 LUCAS ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
201 LUCAS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
202 LUCAS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
202 LUCAS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			

207 LUCAS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
211 LUCAS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
219 LUCAS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
225 LUCAS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
238 LUCAS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
245 LUCAS ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
248 LUCAS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
251 LUCAS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
252 LUCAS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
255 LUCAS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1643 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1651 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1759 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1767 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1775 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1783 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1809 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1810 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1817 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1818 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1825 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1826 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1833 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1834 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2223 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2231 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2238 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2239 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2246 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2247 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2254 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2304 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2305 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2312 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2313 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2320 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2321 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2328 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2329 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2436 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2444 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2452 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2460 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2468 LUTHER LOWELL LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
409 LYNN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
420 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
423 LYNN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
430 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
506 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
509 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
514 LYNN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
522 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
523 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
530 LYNN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
600 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
607 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
609 LYNN AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
610 LYNN AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
210 MAERTZ DR-OUTSIDE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
210 MAERTZ DR-RESIDENCE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
210 MAERTZ DR- LAUNDRY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
210 MAERTZ DR-SOFTENER	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

212 MAERTZ DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
214 MAERTZ DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
216 MAERTZ DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
248 MAERTZ DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
254 MAERTZ DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2205 MAGGIE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2207 MAGGIE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2213 MAGGIE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2214 MAGGIE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2215 MAGGIE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2216 MAGGIE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2221 MAGGIE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2222 MAGGIE LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
2223 MAGGIE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2230 MAGGIE LN	n/a	N	Y			Visual Inspection	P	C	C	NL		N/R	N			
2224 MAGGIE LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
2232 MAGGIE LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
701 S MAIN ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
108 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
150 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
200 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
225 N MAIN ST	LA1C151	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
227 N MAIN ST	LA1C143	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
304 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
307 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
312 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
315 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
320 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
322 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
324 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
326 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
331 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
334 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
351 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
354 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
401 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
410 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
411 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
416 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
416 1/2 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
421 N MAIN ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
423 N MAIN ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
426 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
430 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
434 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
436 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
445 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
445 1/2 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
447 N MAIN ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
456 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
503 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
504 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
510 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
524 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
525 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
530 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1724 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1730 N MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 A N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
344 B N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
344 C N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
344 D N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			

344 E N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
415/417 N MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
119 S MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
124 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
127 S MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
204 S MAIN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
212 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
222 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
223 S MAIN ST	LA1C079	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
229 S MAIN ST	LP1C011	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
305 S MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
308 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
313 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
314 S MAIN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
322 S MAIN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
330 S MAIN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
404 S MAIN ST	n/a	N	N	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
405 S MAIN ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
412 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
415 S MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
419 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
420 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
427 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
430 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
495 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
503 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
504 S MAIN ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
512 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
513 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
519 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
520 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
527 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
530 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
612 S MAIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
711 S MAIN ST	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
1606 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1611 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1612 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1614 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1617 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1618 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1623 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1624 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1625 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1629 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1630 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1635 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1636 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1641 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1642 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1644 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1647 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1648 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1651 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1653 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1654 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1655 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1657 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1659 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1660 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1666 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1671 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1672 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1673 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1720 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1721 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1723 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1800 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1801 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1803 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1810 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1811 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1813 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1818 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1819 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1821 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1826 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1827 MANESS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1829 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1834 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1835 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1842 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1843 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1850 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1851 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1858 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1859 MANESS CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
121 N MAPLE ST/NORTH END	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
121 N MAPLE ST/SOUTH END	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 N MAPLE ST #1	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
329 N MAPLE ST #2	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
329 N MAPLE ST #3	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
329 N MAPLE ST #4	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
109 N MAPLE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
113 N MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
205 N MAPLE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
213 N MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 N MAPLE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
222 N MAPLE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
226 N MAPLE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
232 N MAPLE ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
303 N MAPLE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
311 N MAPLE ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
321 N MAPLE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
337 N MAPLE ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
343 N MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 N MAPLE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
353 N MAPLE ST	LA1C072	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
354 N MAPLE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
440 N MAPLE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	Y			
520 N MAPLE ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
523 N MAPLE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
214/216 N MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
112 S MAPLE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
120 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
124 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
202 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
204 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
210 S MAPLE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
216 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
224 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
308 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
311 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

314 S MAPLE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
322 S MAPLE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
150 MAPLEWOOD DR	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
150 MAPLEWOOD DR	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
305 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
313 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
390 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
398 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
406 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
414 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
415 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
422 MAPLEWOOD DR	LA3S133	N	N			Visual Inspection	C	C	C	NL		N/R	N			
430 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
433 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
440 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
443 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
450 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
502 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
507 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
510 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
515 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
518 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
525 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
526 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
535 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
536 MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
65 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
85 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
117 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
122 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
123 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
131 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
138 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
139 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
146 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
147 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
154 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
155 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
162 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
163 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
170 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
171 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
178 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
179 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
204 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
205 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
212 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
213 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
221 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
228 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
229 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
236 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
237 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
244 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
245 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
252 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
253 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
306 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
307 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

314 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
315 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
322 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
323 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
331 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
338 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
339 E MAPLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1441 MARIA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1447 MARIA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1461 MARIA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1467 MARIA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
MARIA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1093 MARTIN ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1115 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1121 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1126 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1127 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1132 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1133 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1138 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1139 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1144 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1145 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1150 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1151 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1157 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1163 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1169 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1175 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1180 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1181 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1335 MARTIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
430 MARY ANN CIR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
474 MARY ANN CIR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
401 MARYANN CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
406 MARYANN CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
409 MARYANN CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
414 MARYANNE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
422 MARY ANN CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
435 MARY ANN CIRCLE	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
438 MARY ANN CIRCLE	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
443 MARY ANN CIRCLE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
446 MARY ANN CIRCLE	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
451 MARY ANN CIRCLE	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
500 MARY ANN CIRCLE	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
125 MARY HAMSMITH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
133 MARY HAMSMITH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
141 MARY HAMSMITH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
149 MARY HAMSMITH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
157 MARY HAMSMITH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
165 MARY HAMSMITH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
173 MARY HAMSMITH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1319 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1320 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1327 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1328 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1335 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1336 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1343 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1344 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1352 MARYWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

217 MASON CT - RESIDENCE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
101 MASON CT	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
120 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
121 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
133 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
134 MASON CT	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
137 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
138 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
141 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
142 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
143 MASON CT	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
147 MASON CT	LA1C076	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
207 MASON CT	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
216 MASON CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
217 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
218 MASON CT	LA1C091	N	Y	unsure	unsure	Visual Inspection	C	C	C	NL		N/R	Y	unsure		
219 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 MASON CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
221 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
223 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
228 MASON CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
229 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
233 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
236 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
239 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
249 MASON CT	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
250 MASON CT	LA1C140	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
255 MASON CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
256 MASON CT	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
262 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
263 MASON CT	LA1C082	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
264 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
267 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 MASON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 MAY ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
221 MAY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
224 MAY ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
258 MAY ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
284 MAY ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
284 MAY ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
1504 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1505 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1512 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1515 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1520 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1525 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1528 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1535 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1536 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1545 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1548 McALLISTER CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
121 McLAREN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
123 McLAREN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
125 McLAREN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
127 McLAREN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
129 McLAREN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
131 McLAREN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
141 McLAREN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
143 McLAREN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

2448 MEADOW CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2451 MEADOW CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2452 MEADOW CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2455 MEADOW CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2459 MEADOW CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2463 MEADOW CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2467 MEADOW CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2471 MEADOW CREEK DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
622 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
625 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
628 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
636 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
642 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
704 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
709 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
712 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
720 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
726 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
729 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
732 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
740 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
804 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
810 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
817 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
818 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
824 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
825 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
832 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
835 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
836 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
845 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
846 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
853 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
854 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
858 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
859 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
867 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
907 MEADOW LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
914 MEADOW LN	LC4T029	N	N			Construction Records	C	C	C	NL		N/R	N			
915 MEADOW LN	LC4T068	N	N			Construction Records	C	C	C	NL		N/R	N			
922 MEADOW LN	LC4T010	N	N			Construction Records	C	C	C	NL		N/R	N			
923 MEADOW LN	LC4T069	N	N			Construction Records	C	C	C	NL		N/R	N			
930 MEADOW LN	LC4T070	N	N			Construction Records	C	C	C	NL		N/R	N			
931 MEADOW LN	LC4T071	N	N			Construction Records	C	C	C	NL		N/R	N			
938 MEADOW LN	LC4T008	N	N			Construction Records	C	C	C	NL		N/R	N			
939 MEADOW LN	LC4T043	N	N			Construction Records	C	C	C	NL		N/R	N			
946 MEADOW LN	LC4T026	N	N			Construction Records	C	C	C	NL		N/R	N			
947 MEADOW LN	LC4T072	N	N			Construction Records	C	C	C	NL		N/R	N			
1002 MEADOW LN	LC4T023	N	N			Construction Records	C	C	C	NL		N/R	N			
1003 MEADOW LN	LC4T024	N	N			Construction Records	C	C	C	NL		N/R	N			
1010 MEADOW LN	LC4T073	N	N			Construction Records	C	C	C	NL		N/R	N			
1011 MEADOW LN	LC4T074	N	N			Construction Records	C	C	C	NL		N/R	N			
1018 MEADOW LN	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1019 MEADOW LN	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1020 MEADOW LN	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1553 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1563 MEADOWBROOK CT	LC4T040	N	N			Construction Records	C	C	C	NL		N/R	N			
1592 MEADOWBROOK CT	LC4T018	N	N			Construction Records	C	C	C	NL		N/R	N			
1602 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1603 MEADOWBROOK CT	LC4T075	N	N			Construction Records	C	C	C	NL		N/R	N			
1606 MEADOWBROOK CT	LC4T076	N	N			Construction Records	C	C	C	NL		N/R	N			

1607 MEADOWBROOK CT	LC4T077	N	N			Construction Records	C	C	C	NL		N/R	N			
1610 MEADOWBROOK CT	LC4T078	N	N			Construction Records	C	C	C	NL		N/R	N			
1611 MEADOWBROOK CT	LC4T079	N	N			Construction Records	C	C	C	NL		N/R	N			
1615 MEADOWBROOK CT	LC4T041	N	N			Construction Records	C	C	C	NL		N/R	N			
1803 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1806 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1807 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1810 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1811 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1813 MEADOWBROOK CT	LC4T019	N	N			Construction Records	C	C	C	NL		N/R	N			
1815 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1818 MEADOWBROOK CT	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1565 MEDITERANEAN DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1680 MEDITERRANEAN DR #101	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1680 MEDITERRANEAN DR #103	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1680 MEDITERRANEAN DR #104	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1680 MEDITERRANEAN DR #105	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1680 MEDITERRANEAN DR #107	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1705 MEDITERRANEAN DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1830 MEDITERRANEAN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1830 MEDITERRANEAN DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1740 MEDITERRANEAN DR/#101	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1815 MEDITERRANEAN DR/#101	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1740 MEDITERRANEAN DR/#102	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1815 MEDITERRANEAN DR/#102	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1820 MERCANTILE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1825 MERCANTILE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1825 MERCANTILE DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1925 MERCANTILE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
465 MERRY OAKS DR/IRRIG	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
207 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
214 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
222 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 MERRY OAKS DR	n/a		N			Visual Inspection	C	C	C	NL		N/R	N			
231 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
238 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
239 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
246 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
300 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
308 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
316 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 MERRY OAKS DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
332 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
340 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
345 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
348 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
356 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
361 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
364 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
369 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
372 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
380 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
455 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
465 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
470 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
475 MERRY OAKS DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1004 MICHAEL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1012 MICHAEL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1013 MICHAEL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1020 MICHAEL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1021 MICHAEL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1028 MICHAEL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2127 MIDLANDS CT/ #101	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2127 MIDLANDS CT/ #102	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2128 MIDLANDS CT/101&102	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2128 MIDLANDS CT/#103	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2128 MIDLANDS CT/#106	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2111 MIDLANDS CT	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
2120 MIDLANDS CT	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
2127 MIDLANDS CT	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2127 MIDLANDS CT	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
2127 MIDLANDS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2128 MIDLANDS CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
MILAN DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1111 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1117 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1123 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1129 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1135 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1141 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1233 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1239 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1245 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1251 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1257 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1263 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1365 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1371 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1377 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1383 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1389 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1395 MILAN DRIVE NORTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1112 MILAN DRIVE SOUTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1118 MILAN DRIVE SOUTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1124 MILAN DRIVE SOUTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1130 MILAN DRIVE SOUTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1136 MILAN DRIVE SOUTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1142 MILAN DRIVE SOUTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1234 MILAN DRIVE SOUTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1240 MILAN DRIVE SOUTH	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1246 MILAN DRIVE SOUTH	n/a	N	N													

228 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
230 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
232 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
302 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
304 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
306 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
308 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
310 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
318 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
320 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
322 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
324 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
326 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
328 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
340 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
342 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
348 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
350 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
356 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
358 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
364 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
366 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
372 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
374 MILLBRIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
149 MILLIE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
156 MILLIE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
157 MILLIE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
164 MILLIE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
165 MILLIE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
172 MILLIE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
173 MILLIE CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
701 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
703 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
705 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
706 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
708 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
710 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
712 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
715 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
717 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
719 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
720 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
721 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
722 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
723 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
724 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
725 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
726 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
727 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
728 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
729 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
731 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
733 NANCY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
502 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
509 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
510 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
517 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
518 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
525 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
532 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
533 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				
603 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N				

611 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
619 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
626 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
627 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
635 NATHAN LATTIN LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1928 NATIOINAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1937 National St	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1821 NATIONAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1829 NATIONAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1837 NATIONAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1905 NATIONAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1920 NATIONAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1936 NATIONAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1945 NATIONAL ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
910 NICOLE PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
911 NICOLE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
918 NICOLE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
919 NICOLE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
926 NICOLE PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
927 NICOLE PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
935 NICOLE PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
112 NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
141 NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
143 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
145 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
208 NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
218 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
222 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
225 NORTH AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
226 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
231 NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
237 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
238 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
245 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
248 NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
249 NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
249 1/2 NORTH AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
263 NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
301 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
305 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
311 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
311 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
315 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
319 NORTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
320 NORTH AVE	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
325 NORTH AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
329 NORTH AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
333 NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
335 NORTH AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
351 NORTH AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
205 E NORTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
106 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
124 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
132 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
140 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
204 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
212 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
228 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
402 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
410 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

418 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
426 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
512 NORTHGATE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
520 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
528 NORTHGATE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
535 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
536 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
543 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
544 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
551 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
552 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
603 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
604 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
611 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
612 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
619 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
710 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
718 NORTHGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
925 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1019 NOTTINGHAM RD	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1043 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
909 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
917 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
933 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1011 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1027 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1035 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1051 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1059 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1101 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1109 NOTTINGHAM RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1509 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1511 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1517 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1518 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1520 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1525 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1526 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1528 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1533 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1609 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1617 OAK LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

2270 OAKLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2290 OAKLAND DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2180 OAKLAND DR/UNIT B	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2180 OAKLAND DR/UNIT C	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2180 OAKLAND DR/UNIT D	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
202 OHIO GROVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
210 OHIO GROVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
218 OHIO GROVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 OHIO GROVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
226 OHIO GROVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
535 OLIN H SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
455 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
465 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
475 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
515 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
525 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
545 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
555 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
565 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
570 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
575 OLIN H. SMITH DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
311 ORCHARD LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
312 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
318 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
323 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
335 ORCHARD LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
336 ORCHARD LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
341 ORCHARD LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
342 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
349 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
355 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
356 ORCHARD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
361 ORCHARD LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
305 OSCAR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
306 OSCAR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
311 OSCAR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 OSCAR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 OSCAR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
113 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
119 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
121 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
122 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
123 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
127 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
203 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
211 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
212 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 E OTTAWA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
307 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 E OTTAWA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
320 E OTTAWA ST	LC4T012	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 E OTTAWA ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
332 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 E OTTAWA ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
335 E OTTAWA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			

345 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 E OTTAWA ST	LC4T007	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
353 E OTTAWA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
359 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
360 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
367 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
370 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
377 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
380 E OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
118 W OTTAWA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
119 W OTTAWA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
124 W OTTAWA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
125 W OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
129 W OTTAWA ST	LA1C123	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
134 W OTTAWA ST	LA1C122	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
205 W OTTAWA ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
315 W OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 W OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 W OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
327 W OTTAWA ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
329 W OTTAWA ST	LA3R116	N	N	2006	2006	Construction Records	C	C	C	NL		N/R	Y	2006		
330 W OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
413 W OTTAWA ST	LA1C135	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
416 W OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
419 W OTTAWA ST	n/a	N	Y	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
420 W OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
424 W OTTAWA ST	n/a	N	Y	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
425 W OTTAWA ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
429 W OTTAWA ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
2205 OVERLAND RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2213 OVERLAND RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2221 OVERLAND RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2229 OVERLAND RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2237 OVERLAND RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2245 OVERLAND RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2253 OVERLAND RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1102 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1106 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1110 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1113 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1114 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1119 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1120 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1125 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1126 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1131 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1132 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1137 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1138 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1143 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1144 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1149 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1150 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1156 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1157 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1162 OXFORD CIRCLE	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1163 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1168 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1169 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1174 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1175 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1180 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1181 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1185 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1186 OXFORD CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 E PAGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
122 E PAGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
125 E PAGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
202 E PAGE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
351 E PAGE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
118 W PAGE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
216 W PAGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
228 W PAGE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
228 W PAGE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
1314 PARIS BLVD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
316 PARK AVE	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
320 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
406 1/2 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
406 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
412 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
416 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
422 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
428 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
434 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
434 1/2 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
438-440 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
445 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
446 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
446 1/2 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
458 PARK AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
501 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
507 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
511 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
517 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
521 PARK AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
525 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
528 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
603/605 PARK AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
604 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
606 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
611 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
622 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
628 PARK AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
703 PARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
713 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
714 PARK AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
719 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
722 PARK AVE	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
723 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
727 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
728 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
732 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
733 PARK AVE	LA1C093	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
737 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
738 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
740 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
745 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
746 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
751 PARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
777 PARK AVE	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
821 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

821 PARK AVE	n/a	N	Y			Construction Records	U	U	O	NL		N/R	N			
1044 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1054 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1101 PARK AVE	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
1101 PARK AVE	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1140 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1375 PARK AVE	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
1375 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1530 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1606 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1611 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1612 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1617 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1618 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1623 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1624 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1629 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1630 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1631 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1635 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1636 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1637 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1641 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1643 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1647 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1649 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1653 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1659 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1710 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1711 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1720 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1721 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1800 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1801 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1810 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1811 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1818 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1819 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1826 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1827 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1834 PARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1835 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1842 PARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

340 PARKER ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
341 PARKER ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
610 PARKMOOR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
613 PARKMOOR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 PARKMOOR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
617 PARKMOOR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 PARKMOOR CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1139 PARKSIDE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
305 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
311 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
319 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
327 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
330 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
331 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
338 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
339 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
349 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
350 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
357 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
365 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
370 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
371 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
379 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
380 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
385 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
390 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
395 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
401 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
404 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
409 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
415 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
423 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
430 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
431 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
440 PARKSIDE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
500 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
503 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
506 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
516 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
519 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
524 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
604 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
609 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
612 PARKSIDE DR	n/a	N	N													

1724 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1725 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1850 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1851 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1858 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1859 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1866 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1867 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1902 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1903 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1910 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1918 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1926 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1934 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1935 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1942 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1943 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1950 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1951 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1951 PARKSIDE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
571 SOUTH PEACE RD	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
661 S PEACE RD SUITE 101	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
661 S PEACE RD #117	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1470 S PEACE RD/#101	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1470 S PEACE RD/#102	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1470 S PEACE RD/#104	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/103	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 W PEACE RD/IRRIGATION	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/#101	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/#102	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/#104	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/#105	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/#106	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/#107	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/#108	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
265 W PEACE RD/CAFE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
400 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
402 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
404 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
406 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
410 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
412 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
414 S PEACE RD	n/a	N	N			Visual										

[illegible]

646 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
648 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
650 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
652 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
660 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
662 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
664 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
668 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
670 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
672 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
674 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
680 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
682 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
684 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
686 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
688 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
690 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
692 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1450 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1450 S PEACE RD	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1475 S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
S PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
115 W PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 W PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 W PEACE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1706 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1714 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1715 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1722 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1723 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1730 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1731 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1738 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1739 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1744 PEBBLEWOOD CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1502 PEBBLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1505 PEBBLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1510 PEBBLEWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1618 PEBBLEWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1625 PEBBLEWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1626 PEBBLEWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1627 PEBBLEWOOD DR	n/a	N	N			Construction Records	C	C	C	NL		N/R	N			
1634 PEBBLEWOOD DR	LC4T015	N	N			Construction Records	C	C	C	NL		N/R	N			
110 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
112 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
113 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
114 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
115 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
116 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
117 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
119 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
122 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
123 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
124 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
125 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
126 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
127 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
129 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
130 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
132 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
133 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
134 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
135 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
136 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
137 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
139 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
140 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
142 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
143 PENNY LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
144 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
145 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
146 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
147 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
149 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
150 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
152 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
153 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
154 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
155 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
156 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
157 PENNY LN	n/a	N	N													

[illegible]

1157 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1158 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1159 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1160 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1165 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1166 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1167 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1168 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1173 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1174 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1175 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1176 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1181 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1183 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1189 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1191 PENNY LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
304 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
305 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
314 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
315 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
322 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
323 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
332 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
341 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
345 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1801 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1811 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1814 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1819 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1822 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1825 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1830 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1833 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1838 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1843 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1844 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1851 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1852 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1859 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1860 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1870 PERRY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1900 PERRY CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
19																

1625 PINE TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1626 PINE TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1634 PINE TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2301 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2309 PIONEER WAY	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2310 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2317 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2318 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2325 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2326 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2333 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2334 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2341 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2342 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2349 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2357 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2365 PIONEER WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
105 PLANK RD/IRRIGATION	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
105 PLANK RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
165 E PLANK RD	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
165 E PLANK RD	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
610 PLAZA DR/#1	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 PLAZA DR/#2	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 PLAZA DR/#3	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 PLAZA DR/#4	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
610 PLAZA DR/#5	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 PLAZA DR/#7	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 PLAZA DR/#8	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 PLAZA DR/#5	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 PLAZA DR/#6	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 PLAZA DR/#4	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 PLAZA DR/#2	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
630 PLAZA DR/#1	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
605 PLAZA DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
645 PLAZA DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
665 PLAZA DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
315 PLEASANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 PLEASANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
329 PLEASANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 PLEASANT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
335 PLEASANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 PLEASANT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
339 PLEASANT ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
340 PLEASANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
341 PLEASANT ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
346 PLEASANT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
301 PLYMOUTH CT	LP1C001	N	N	2010	2010	Construction Records	C	C	C	NL		N/R	Y	2010		
311 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
318 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
323 PLYMOUTH CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
326 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
335 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
345 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
353 PLYMOUTH CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
358 PLYMOUTH CT	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1019 POTOMAC AVE	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1002 POTOMAC AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1010 POTOMAC AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1018 POTOMAC AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1026 POTOMAC AVE	n/a		N			Visual Inspection	C	C	C	NL		NR	N			
1027 POTOMAC AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1034 POTOMAC AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
PRAIRIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1401 S PRAIRIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1551 S PRAIRIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1600 S PRAIRIE DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1631 S PRAIRIE DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1800 S PRAIRIE DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
920 W PRAIRIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
955 W PRAIRIE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1350 W PRAIRIE DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1350 W PRAIRIE DR	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1842 PRESIDENTIAL PKWY	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1810 PRESIDENTIAL PKWY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1818 PRESIDENTIAL PKWY	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1826 PRESIDENTIAL PKWY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1834 PRESIDENTIAL PKWY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1900 PRESIDENTIAL PKWY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1908 PRESIDENTIAL PKWY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1936 PRESIDENTIAL PKWY	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
1940 PRESIDENTIAL PKWY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
4 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
5 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
6 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
7 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
8 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
9 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
10 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
11 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
12 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
13 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
14 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
15 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
16 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
17 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
18 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
19 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
20 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
21 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
22 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
23 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
24 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
25 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
26 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
27 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
28 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
29 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
30 PRIMROSE LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
541 PURI PKWY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
541 PURI PKWY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
207 RACHEL CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
214 RACHEL CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 RACHEL CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
222 RACHEL CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
223 RACHEL CIRCLE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1720 RAINTREE CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

119 RESTON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 RESTON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
127 RESTON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
128 RESTON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
135 RESTON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
136 RESTON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
144 RESTON CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1350 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1352 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1354 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1356 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1420 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1421 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1422 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1423 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1424 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1425 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1426 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1427 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1440 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1442 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1444 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1446 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1451 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1453 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1455 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1457 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1460 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1462 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1464 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1466 RIDGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
209 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
225 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
228 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
233 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
241 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
315 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
316 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
327 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
333 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
339 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
340 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
347 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
348 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
355 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
356 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
363 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
371 ROGERS WAY	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
615 ROOSEVELT CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 ROOSEVELT CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
619 ROOSEVELT CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 ROOSEVELT CT	n/a	N	Y	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
622 ROOSEVELT CT	LA1C152	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
623 ROOSEVELT CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
628 ROOSEVELT CT	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
631 ROOSEVELT CT	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
632 ROOSEVELT CT	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		

[illegible]

489 ROWANTREE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1610 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1611 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1618 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1619 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1627 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1635 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1701 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1704 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1709 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1712 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1717 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1720 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1725 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1728 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1733 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1736 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1741 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1744 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1749 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1752 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1757 RUSSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
105 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
109 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
113 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
114 SABIN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
117 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
125 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
126 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
131 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
133 SABIN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
135 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
140 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
143 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
150 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
160 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
202 SABIN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
206 SABIN ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
212 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
213 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
225 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
226 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
229 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 SABIN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 N SACRAMENTO ST/#1	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 N SACRAMENTO ST/#2	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
336 N SACRAMENTO ST/#3	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 N SACRAMENTO ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
213 N SACRAMENTO ST	LC1T003	N	N			Visual Inspection	L	L	L	L		5/7/24	N			4/29/2024
218 N SACRAMENTO ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
230 N SACRAMENTO ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
303 N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
303 1/2 N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
313 N SACRAMENTO ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
317 N SACRAMENTO ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
324 N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 N SACRAMENTO ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
326 N SACRAMENTO ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
329 N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

335 N SACRAMENTO ST	LA1C081	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
342 N SACRAMENTO ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
347 N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
360 N SACRAMENTO ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
235 A N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 B N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 C N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 D N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 E N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 F N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
255 A N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
255 B N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
255 C N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
255 D N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
255 E N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
255 F N SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
118 S SACRAMENTO ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
127 S SACRAMENTO ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
131 S SACRAMENTO ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
135 S SACRAMENTO ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
139 S SACRAMENTO ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
203 S SACRAMENTO ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
405 SAM DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
420 SAM DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
425 SAM DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
445 SAM DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
505 SAM DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1437 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
601 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
608 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
609 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
617 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
624 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
625 SANDBERG DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
632 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
633 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
640 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
641 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
649 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
656 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
657 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
664 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
665 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
672 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
705 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
712 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
713 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
720 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
729 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
736 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1442 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1450 SANDBERG DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1361 SANDCASTLE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1380 SANDCASTLE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1360 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1366 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1367 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1372 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1386 SANDCASTLE DR	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1391 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1394 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1416 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1424 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1432 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1440 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1448 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1456 SANDCASTLE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
902 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
913 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
921 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
929 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
937 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
938 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
940 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
945 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1001 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1002 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1004 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1009 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1010 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1012 SCOTT DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2030 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2032 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2034 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2035 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2036 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2037 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2039 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2040 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2041 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2042 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2044 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2045 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2046 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2047 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2049 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2051 SOMERSET LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2055 SOMERSET LN	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
2057 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2059 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2061 SOMERSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
111 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
116 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
126 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
204 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
218 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
219 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
222 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
229 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
304 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
305 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
312 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
313 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
327 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
328 SOMONAUK ST	LA1C144	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
405 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
408 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
413 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
420 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
421 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		

431 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
432 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
437 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
440 SOMONAUK ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
445 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
446 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
450 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
453 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
464 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
508 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
575 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
608 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
614 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
615 SOMONAUK ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
708 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
714 SOMONAUK ST	LC4T017	N	N			Visual Inspection	C	C	C	NL		N/R	N			
719 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
726 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
727 SOMONAUK ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
804 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
805 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
807 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
812 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
813 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
818 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
821 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
822 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
825 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
826 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
827 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
900 SOMONAUK ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
905 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
906 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
912 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
913 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
919 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
922 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
925 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
930 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
936 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
939 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1004 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1014 SOMONAUK ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
1015 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1020 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1024 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1025 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1030 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1034 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1040 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1044 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1045 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1048 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1104 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1105 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1108 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1112 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1118 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1121 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1124 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1128 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1134 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			

1140 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1144 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1153 SOMONAUK ST	LA1C141	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
1213 SOMONAUK ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1220 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1221 SOMONAUK ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1222 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1228 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1231 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1232 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1245 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1440 SOMONAUK ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
1440 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1445 SOMONAUK ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
340 SOUTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
340 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
411 SOUTH AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
611 SOUTH AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
612 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
618 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
624 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
627 SOUTH AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
633 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
634 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
635 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
640 SOUTH AVE	LA1C149	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
641 SOUTH AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
644 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
645 SOUTH AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
654 SOUTH AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
655 SOUTH AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
660 SOUTH AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
661 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
664 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
665 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
672 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
673 SOUTH AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
679 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
686 SOUTH AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
816 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
612 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
616 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 SOUTH CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
622 SOUTH CROSS ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
626 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
627 SOUTH CROSS ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
629 SOUTH CROSS ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
630 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
635 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
638 SOUTH CROSS ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
641 SOUTH CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
703 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
704 SOUTH CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
709 SOUTH CROSS ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
710 SOUTH CROSS ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
715 SOUTH CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
716 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
719 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
720 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1009 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1009 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1020 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1026 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1031 SOUTH CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1032 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1036 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1037 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1038 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1039 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1043 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1044 SOUTH CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1046 SOUTH CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1047 SOUTH CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1050 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1051 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1055 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1061 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1066 SOUTH CROSS ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1104 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1110 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1115 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1125 SOUTH CROSS ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
427 SPARTAN TR	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
427 SPARTAN TR	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
427 SPARTAN TR	n/a	Y	Y			Construction Records	O	O	O	NL		N/R	N			
803 STANLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
804 STANLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
811 STANLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
812 STANLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
819 STANLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
820 STANLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
828 STANLEY CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1469 STARFISH LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R				
1487 STARFISH LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R				
1460 STARFISH LN	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1470 STARFISH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1475 STARFISH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1480 STARFISH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1481 STARFISH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1493 STARFISH LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
211 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 STARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
410 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
416 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
417 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
418 STARK AVE	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
423 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
426 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
427 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
427 1/2 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
440 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
441 STARK AVE	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
448 STARK AVE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
454 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
460 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
466 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
472 STARK AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
584 W STATE	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
227 E STATE ST/#909	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1330 E STATE ST/UNIT A	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 W STATE ST/UPSTAIRS	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
106 E STATE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
202 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

212 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
220 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
222 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
228 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
232 E STATE ST	n/a	N	Y	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
303 E STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
309 E STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
310 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
310 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
310 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
310 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
310 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
310 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
310 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
310 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
313 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
319 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
331 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
343 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
403 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
404 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
412 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
416 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
426 1/2 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
426 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
439 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
442 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
449 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
450 1/2 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
450 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
453 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
458 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
459 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
464 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
465 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
471 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
474 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
477 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
482 E STATE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
483 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
486 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
491 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
494 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
499 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
500 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
503 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
516 E STATE ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
526 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
546 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
605 E STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
620 E STATE ST	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
625 E STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
675 E STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
725 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
735 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
910 E STATE ST	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			

910 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1115 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1135 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1150 E STATE ST	LC4T027	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1170 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1190 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1250 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1280 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1330 E STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
114 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
116 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
133 W STATE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
134 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
156 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
201 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
202 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
211 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 1/2 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
216 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 1/2 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
223 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
223 1/2 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
229 1/2 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
230 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
233 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
239 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
245 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
247 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
303 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
308 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
313 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
322 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
326 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
327 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 1/2 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
331 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
332 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
336 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
337 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
338 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
341 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
352 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
352 1/2 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
355 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
360 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
362 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
366 W STATE ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
404 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
407 W STATE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
407 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
418 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
422 W STATE ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
425 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
437 W STATE ST	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			

508 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
511 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
513 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
519 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
521 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
529 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
530 W STATE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
533 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
539 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
547 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
550 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
556 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
557 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
563 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
568 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
571 W STATE ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
571 1/2 W STATE ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
589 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
593 W STATE ST	LA3R112	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
594 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
599 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
603 W STATE ST	LA1C145	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
612 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
617 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
623 W STATE ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
627 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
630 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
631 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
704 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
711 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
715 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
721 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
724 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
729 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
735 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
740 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
743 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
801 W STATE ST	LA3R115	N	N	2009	2009	Construction Records	C	C	C	NL		N/R	Y	2009		
815 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
903 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
904 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
909 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
912 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
915 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
920 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
923 W STATE ST	LA3R112	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
930 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
930 1/2 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
933 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
934 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
940 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
942 W STATE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
947 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
953 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
954 W STATE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
954 W STATE ST	n/a	N	Y			Construction Records	O	O	O	NL		N/R	N			
961 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
964 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
967 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
974 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1001 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1006 W STATE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			

1015 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1021 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1027 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1033 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1039 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1045 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1051 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1770 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1778 W STATE ST	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
307/309 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
229/231 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
801 STEVENS AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
813 STEVENS AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
818 STEVENS AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
819 STEVENS AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
824 STEVENS AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
830 STEVENS AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
831 STEVENS AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
838 STEVENS AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
511 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
513 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
515 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
517 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
519 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
521 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
531 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
533 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
535 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
537 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
551 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
553 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
555 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
557 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
561 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
563 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
565 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
567 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
569 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
571 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
581 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
583 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
585 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
587 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
589 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
591 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
611 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
613 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
615 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
617 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
619 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
621 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
631 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
633 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
635 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
637 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
639 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
641 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
651 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
653 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
655 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
657 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
659 STONEGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

1545 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1547 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1549 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1550 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1551 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1553 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1555 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1556 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1556 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1557 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1558 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1560 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1562 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1563 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1565 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1567 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1567 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1569 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1601 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1631 W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
W STONEHENGE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2215 STRATFORD LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
2220 STRATFORD LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
2231 SRATFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2223 STRATFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2239 STRATFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2321 STRATFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2329 STRATFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2337 STRATFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
809 SUNSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
810 SUNSET LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
830 SUNSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
831 SUNSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
840 SUNSET LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
845 SUNSET LN	n/a	N	Y			Visual Inspection	U	U	C	NL		N/R	N			
856 SUNSET LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
863 SUNSET LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
870 SUNSET LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
875 SUNSET LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
880 SUNSET LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
888 SUNSET LN	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
2201 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2202 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2209 SURREY ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2210 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2217 SURREY ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2218 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2225 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2226 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2233 SURREY ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2234 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2241 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2242 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2308 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2311 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2316 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2319 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2324 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2327 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2332 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

2335 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2340 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2343 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2348 SURREY ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
700 SUSAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
703 SUSAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
808 SUSAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
903 SUSAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1119 SUSAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1127 SUSAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1135 SUSAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1143 SUSAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1116 SWANBERG CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1121 SWANBERG CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1124 SWANBERG CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1129 SWANBERG CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1132 SWANBERG CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3100 SYCAMORE RD	n/a	N	N			Construction Records	O	O	O	NL		N/R	N			
3206 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3212 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3218 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3224 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3230 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3236 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3244 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3254 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3260 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
3272 SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2733B SYCAMORE RD	n/a	Y	N			Visual Inspection	C	C	C	NL		N/R	N			
3248A SYCAMORE RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
110 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
111 E SYCAMORE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
121 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
129 E SYCAMORE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
211 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
212 E SYCAMORE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
220 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
223 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
229 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
235 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
301 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
303 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
304 E SYCAMORE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
311 E SYCAMORE ST	LA1C110	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
312 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
314 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
321 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
322 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
328 E SYCAMORE ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
331 E SYCAMORE ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
337 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
340 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
343 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
344 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
347 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
348 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
352 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
355 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
356 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
360 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

402 E SYCAMORE ST	LA1C139	N	Y	unsure	unsure	Precon Inspection	C	C	C	NL		N/R	Y	unsure		
403 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
409 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
410 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
412 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
415 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
420 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
421 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
505 E SYCAMORE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
506 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
507 E SYCAMORE ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
514 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
518 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		2024	N			
522 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
528 E SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
531 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
539 E SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
208 W SYCAMORE ST	n/a	N	Y	2024	2024	Exploratory dig	C	C	C	NL		2024	Y	2024		
211 W SYCAMORE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
212 W SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
217 W SYCAMORE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
224 W SYCAMORE ST	LP1C003	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
228 W SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
229 W SYCAMORE ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
233 W SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
235 W SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
241 W SYCAMORE ST	LA1C071	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
316 W SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
324 W SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
327 W SYCAMORE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 W SYCAMORE ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
333 W SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
337 W SYCAMORE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
303 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
309 TERRACE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
314 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
317 TERRACE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
320 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
323 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
326 TERRACE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
330 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
338 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
404 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
408 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
411 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
416 TERRACE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
419 TERRACE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
420 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
425 TERRACE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
426 TERRACE DR	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1715 TEWKSBERRY DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
805 THORNWOOD RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1703 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1710 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1711 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1719 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1724 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1727 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1735 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1738 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1743 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1751 THUROW ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

1563 TIMBERWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1565 TIMBERWOOD DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
912 TOWNSEND ST	LA1C087	N	Y	unsure	unsure	Precon Inspection	C	C	C	NL		N/R	Y	unsure		
913 TOWNSEND ST	LA1C088	N	Y	unsure	unsure	Precon Inspection	C	C	C	NL		N/R	Y	unsure		
918 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
921 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
926 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
927 TOWNSEND ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
932 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
933 TOWNSEND ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
937 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
938 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
943 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1007 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1014 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1015 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1017 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1018 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1022 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1023 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1027 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1028 TOWNSEND ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1033 TOWNSEND ST	LA1C131	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1034 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1038 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1039 TOWNSEND ST	LA1C150	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1044 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1048 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1103 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1104 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1107 TOWNSEND ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1108 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1114 TOWNSEND ST	LA1C132	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1115 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1117 TOWNSEND ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
1120 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1123 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1124 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1127 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1128 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1133 TOWNSEND ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1134 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1140 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1143 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1144 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1204 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1205 TOWNSEND ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1213 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1214 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1217 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1218 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1222 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1223 TOWNSEND ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1227 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1228 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1233 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1234 TOWNSEND ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1242 TOWNSEND ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1942 TRUMAN ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1911 TRUMAN ST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
1926 TRUMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1822 TRUMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1830 TRUMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1838 TRUMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1903 TRUMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1918 TRUMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1919 TRUMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1934 TRUMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
243 E TURNER	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
235 E TURNER PL	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
114 E TURNER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
115 E TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
202 E TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
211 E TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
216 E TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
219 E TURNER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
101 W TURNER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
107 W TURNER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
117 W TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
120 W TURNER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
121 W TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
125 W TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
201 W TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
204 W TURNER PL	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
210 W TURNER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
211 W TURNER PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
226 W TURNER PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
110 E VANCE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
111 E VANCE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
203 E VANCE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
105 W VANCE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
108 W VANCE ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
209 W VANCE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 W VANCE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
814 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
815 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
823 VAUGHN CT	LC4T009	N	N			Visual Inspection	C	C	C	NL		N/R	N			
831 VAUGHN CT	LC4T036	N	N			Visual Inspection	C	C	C	NL		N/R	N			
839 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
847 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
850 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
855 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
858 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
905 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
908 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
913 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
916 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
921 VAUGHN CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
509 VICTOR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
510 VICTOR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
513 VICTOR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
517 VICTOR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
518 VICTOR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
521 VICTOR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
522 VICTOR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
525 VICTOR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
526 VICTOR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
529 VICTOR ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
532 VICTOR ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
270 VIDA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
280 VIDA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
295 VIDA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
300 VIDA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
305 VIDA CT	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

315 VIDA CT	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
305 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
310 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
315 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
320 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
325 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
330 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
335 VIKING DR	n/a	N	Y			Visual Inspection	C	P	C	NL		N/R	N			
340 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
345 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
350 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
415 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
420 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
425 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
430 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
435 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
440 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
445 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
450 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
500 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
510 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
520 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
530 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
540 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
550 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
560 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
570 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
575 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
580 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
590 VIKING DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
710 VILLAGIO DR	n/a	Y	N			Construction Records	O	O	O	NL		N/R	N			
105 VISTA TERRACE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
114 VISTA TERRACE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
115 VISTA TERRACE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
125 VISTA TERRACE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
133 VISTA TERRACE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
134 VISTA TERRACE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
144 VISTA TERRACE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
145 VISTA TERRACE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
151 VISTA TERRACE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
152 VISTA TERRACE	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
157 VISTA TERRACE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
158 VISTA TERRACE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
233 W STATE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 N WALNUT ST	n/a	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
126 N WALNUT ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
132 N WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
218 N WALNUT ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
311 N WALNUT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
324 N WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
120 S WALNUT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
204 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
212 S WALNUT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
217 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
219 S WALNUT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
220 S WALNUT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
310 S WALNUT ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
311 S WALNUT ST	LA1C130	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
320 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
321 S WALNUT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
326 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
327 S WALNUT ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		

329 S WALNUT ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
404 S WALNUT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
407 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
411 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
412 S WALNUT ST	LP1C019	N	N	1996	1996	Construction Records	C	C	C	NL		N/R	Y	1996		
425 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
426 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
429 S WALNUT ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
436 S WALNUT ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
408 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
412 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
418 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
423 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
424 WASHINGTON PL	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
428 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
433 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
438 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
439 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
444 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
445 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
452 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
453 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
459 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
462 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
502 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
509 WASHINGTON PL	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
512 WASHINGTON PL	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
515 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
517 WASHINGTON PL	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
518 WASHINGTON PL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2102 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2104 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2106 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2108 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2112 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2114 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2116 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2118 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2122 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2124 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2126 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2128 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2129 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2129 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2132 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2134 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2136 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2138 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2141 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2143 WATERBURY LN EAST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2145 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2147 WATERBURY LN EAST	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
2152 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2154 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2156 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2158 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2161 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2163 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2165 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2167 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2172 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2174 WATERBURY LN EAST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

[illegible]

502 WEST ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		N/R	Y	2024		
503 WEST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
507 WEST ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
513 WEST ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
329 WHITE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
337 WHITE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
445 WHITE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
453 WHITE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
461 WHITE ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
240 Whittmore Drive	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
210 WHITEMORE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2203 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2211 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2219 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2227 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2230 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2235 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2238 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2243 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
2246 WICKFORD LN	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1003 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1008 WILD ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
1011 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1014 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1017 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1018 WILD ST	n/a	N	Y	2023	2023	Visual Inspection	C	C	C	NL		N/R	Y	2023		
1023 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1024 WILD ST	n/a	N	Y	2024	2024	Visual Inspection	C	C	C	NL		2024	Y	2024		
1027 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1028 WILD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
1030 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1033 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1037 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1038 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1048 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1107 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1108 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1110 WILD ST	n/a	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	Y	2022		
1111 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1114 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1117 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1121 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1127 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1128 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1133 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1134 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1137 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1138 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1143 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1144 WILD ST	LC1T002	N	N			Visual Inspection	L	L	L	L		5/7/24	N		Yes	4/29/2024
1207 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1208 WILD ST	LC4T014	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1213 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1214 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1217 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1218 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1223 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1224 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1226 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1227 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1228 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1233 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1241 WILD ST	n/a	N	Y			Visual Inspection	C	C	C	NL		N/R	N			
1323 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1331 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1339 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1347 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1405 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1415 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1416 WILD ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
106 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
109 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
114 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
122 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
204 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
212 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
215 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
220 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
223 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
228 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
236 WILKINS RD	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1305 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1313 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1320 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1321 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1328 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1329 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1336 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1337 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1344 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1345 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1406 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1407 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1414 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1415 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1422 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1423 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1430 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1431 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1438 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1439 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1446 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1447 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1454 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1455 WILLIAM ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

[illegible]

1613 WOODGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1617 WOODGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1621 WOODGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1625 WOODGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1750 WOODGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1761 WOODGATE DR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
496 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
506 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
514 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
521 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
522 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
529 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
530 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
538 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1500 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1508 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1511 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1516 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1526 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1534 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1619 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1624 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1627 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1632 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1635 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1640 WOODLAND TRAIL	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST - #1	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST - #2	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST - #3	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST - #4	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST - #5	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST - #6	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST - #7	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST - #8	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
432 WYMAN ST- SFTNR	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
411 WYMAN ST	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
413 WYMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
421 WYMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
424 WYMAN ST	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1104 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1111 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1119 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1120 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1127 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1135 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1136 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1209 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1217 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1218 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1225 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1226 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1233 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1234 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1307 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1308 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1315 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1316 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1323 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1324 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1331 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1339 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1340 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			

1347 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1348 YORKSHIRE DR N	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1122 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1129 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1130 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1137 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1138 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1215 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1216 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1223 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1224 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1231 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1232 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1239 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
1240 YORKSHIRE DR S	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
662 ZAGREB AVE	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
608 ZAGREB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			
620 ZAGREB AVE	n/a	N	N			Visual Inspection	P	C	P	NL		N/R	N			
632 ZAGREB AVE	n/a	N	Y			Visual Inspection	P	C	P	NL		N/R	N			
644 ZAGREB AVE	n/a	N	N			Visual Inspection	C	C	C	NL		N/R	N			